

Index

- abrasion damage to acrylic, 18
- absolute altitude, 34
- acceleration errors,
 - attitude indicators, 40–41
 - magnetic compass, 57–58
- actuators, hydraulic systems, 274–275, **274**, 278
- advance, engine timing, 80, 87–88, 89
- agonic line of magnetic variation, 59
- ailerons, airframe inspection, 4
- air conditioning, 243–246, **245**, 251
- air cooling, 82–83
- air filters, 111
- air in hydraulic fluid, 277, 278–279
- airfoil properties of propellers, 201, 202, **203**, 215
- airframes, 1–26
 - ailerons, 4
 - antennas, 23–26
 - attrition, 2, 4
 - cabling, 4
 - cleanliness of exterior, 3
 - cracks, 4
 - deformation of structure, 4
 - elevators, 4
 - emergency locator transmitter (ELT), 20–23
 - engine cowling, 4
 - exhaust system, 5
 - foreign object damage (FOD), 2
 - friction and wear, 4
 - heat damage, 5
 - hinges, 4
 - interior preflight inspection, 13–14
 - leaks and drips, 2, 3, 105
 - lighting systems, 8–13
 - oil canning in exterior skin, 5
 - overload effects on airframe, 4–5
- airframes (*Cont.*):
 - paint blisters, peeling, 5
 - preflight inspection, 1–8, 1
 - rivets, popped, 3, **3**, 5
 - rudders, 4
 - rust and corrosion, 6–8
 - security, 2
 - speed fairings, 3
 - stains on exterior of aircraft, 3
 - transparencies (windows), 14–20
 - vibration damage, 5–6
 - weather's effects on airframe, 4
 - wrinkles in exterior skin, 5
- airspeed indicators, 27–30, **29**, **30**
 - blocked pitot tubes, 28
 - blocked static port, 28–29
 - calibrated airspeed (CAS), 29–30
 - equivalent airspeed (EAS), 29–30
 - icing, 28
 - machmeters, 29
 - preflight inspection, 38
 - ram vs. ambient (static) air pressure, 27
 - true airspeed (TAS), 29–30
 - vertical velocity indicator (VVI), 35, **35**, **36**, 39
- airworthiness, 67–68
- alternators, 61, 80, 168–172, **169**, 175–176, 187–188, 194
- altimeters, 30–34, **32**, **33**
 - absolute altitude, 34
 - airport elevation above sea level, 31
 - counter pointer altimeters, 31, 33
 - density altitude, 34
 - diaphragms, 31
 - drum pointer altimeters, 31, **33**
 - failure of altimeters, substituting other devices, 34
 - flight levels, 34