

## INDEX

- radio frequency interference (RFI),  
lighting systems causing, 12
- radios, 25
- ram vs. ambient (static) air pressure,  
pitot tube, 27, 36–37
- random drift, heading indicators, 41, 50
- rebuilt engines, 65
- regulators, voltage regulators, 174
- Renegade amphibian, 7
- repairs, unscheduled maintenance, 72, 75  
(*See also* preventive maintenance)
- replacement parts, 64, 68–72
- reservoir for hydraulic fluid, 273
- reversed polarity, battery explosion, 158
- revolutions per minute (RPM),  
propellers, 202, 207–208, 210, 213
- rich-lean setting, 79, 81–82, 97–98, 108,  
130, 139, 143, 144–145, 147, 148
- rivets, popped, 3, 5
- rolamite switch, in ELTs, 21
- Rolls Royce Griffon engine, 78
- RPM settings, for engine, 81
- rubber bladder type fuel tanks, 134
- rudders, airframe inspection, 4
- rust  
airframe inspection, 6–8  
cleansing properties of oil, 116, 122
- scale error, in altimeters, 33
- schematics of electrical system, 185, 186
- security, 2
- series circuits, 152
- series-parallel circuits, 152
- single-disc brakes, 230–232, 233
- sliding mass switch, in ELTs, 21
- slip indicator (*see* turn indicator)
- smoke from exhaust, 139
- Society of Automotive Engineers (SAE)  
ratings, oil, 115
- solenoid, starter motor activation, 181
- spark plugs, 80, 87, 90–94, 91, 92, 94,  
110, 122
- specific gravity (SPGR), batteries,  
157–161, 162, 163
- speed fairings, 3
- Spitfire, Rolls Royce Griffon engine, 78
- stains on exterior of aircraft, 3
- staking a rocker valve, 111
- standard atmospheric pressure chart, 251
- standby vacuum system (SVS),  
pneumatic systems, 288
- starters, 179–184, 183, 194–195, 199–200
- static errors, magnetic compass, 56
- static port, 37–38
- stoichiometric combustion, exhaust  
gases, 97
- storage of aircraft, corrosion protection, 7
- stretched acrylic transparencies  
(windows), 15–16
- strobe lights, 10–12, 11
- superchargers, 101, 141–142, 142  
(*See also* turbocharger systems)
- supplemental type certificates (STCs), 68
- swinging the compass, 56
- tachometers, 101, 103, 108
- thermal cracking process for gasoline, 129
- thermal runaway, 168
- thrust, propellers, 215
- time between overhaul (TBO), engines,  
63–64, 145
- timing, engines, 79, 80, 89
- tires, 222–229, 223
- TKS Weeping Wing anti-icing system,  
266–268, 267
- top dead center (TDC), 80, 87
- torque, propellers, 215
- tractor propellers, 201–202
- transparencies (windows), 14–20  
abrasion damage to acrylic, 18  
acrylic (Plexiglas) transparencies, 15  
bird strikes, 16  
cleaning acrylic transparencies, 16–17  
crazing, 15–16, 19–20  
delamination of transparencies, 18–19  
glare rings in windows, 17  
glass windows, 14–15  
laminated acrylic, 16  
noise suppression, 15  
polishes and waxes, 17  
preflight inspection, 14–20  
replacing acrylic transparencies, 18  
restoration of crazed transparencies, 20  
scratches, 14–15, 17  
stretched acrylic transparencies, 15–16  
ultraviolet light damage to acrylic,  
17–18  
water damage to acrylic, 18
- transponders, 25
- true airspeed (TAS), 29–30
- turbine wheel, turbocharger systems, 143
- turbocharger systems, 141–150  
bootstrapping, 146