

- turbocharger systems (*Cont.*):  
 Cessna TU206G turbocharger, **145**  
 changing the oil, 150  
 contaminants in cooling fluid, 148, 150  
 control of turbocharger, 145  
 cylinder head temperature (CHT)  
   gauges, 147–148  
 cylinders, 144–145  
 exhaust gas temperature (EGT)  
   gauges, 147–148  
 failure, emergency procedures, 150  
 flow diagram, **144**  
 fuel-air mixture, 143, 144–145, 147, 148  
 heat problems, 147–148  
 high-altitude operation, 144  
 historical development of super- and  
   turbo-charging, 142  
 impeller, 143  
 leaks, 150  
 lubrication, 148, 150  
 maintaining sea level power, 142–143  
 manifold pressure (m.p) gauges, 146  
 misconceptions, 144–145  
 overboosting, 146, 150  
 pistons, 144–145  
 rich-lean setting, 143, 144–145, 147,  
   148  
 superchargers, 101, 141–142, **142**  
 time between overhaul (TBO), 145  
 troubleshooting, 148–150  
 turbine wheel, 143  
 vibrations, 150  
 wastegate controller, 145–147  
 wear on engine, 144–145
- turn indicators, 42–44, **43**  
   errors, acceptable ranges, 51  
   preflight inspections, 49
- turning error, magnetic compass, 57
- type certificate data sheets (TCDSs), 68
- ultra high frequency (UHF) antennas, 25
- ultraviolet light damage to acrylic  
   transparencies (windows), 17–18
- vacuum-pump driven gyro systems, 45,  
   **46, 47, 50, 61, 283–284, 283, 284**
- valves, 111
- vapor lock, 87, 108, 131, 139
- variable isobaric systems, pressurization  
   systems, 249–251
- variation, magnetic, lines of, 58–59, **58**
- velocity (air) cooling, 82–83
- vents, fuel tank, 134–135
- venturi-driven gyro systems, 44–45, **44,**  
   47, 49, 50, 281
- vertical velocity indicator (VVI), 35, **35,**  
   **36, 39**
- very high frequency (VHF) antennas, 25
- vibration damage, 5–6, 112  
   friction error in altimeters, 33  
   propellers, 214
- viscosity of oil, 110, 111, 115–116,  
   121–122, 124
- voltage regulators, 174
- voltmeters, 174
- VOR/LOC, 25
- warranty work, engines, 65–66
- wastegate controller, turbocharger  
   systems, 145–147
- water damage to acrylic, 18
- water in fuel, 134, 135–136
- water in hydraulic fluid, 277
- weather, airframe inspection, 4
- Weeping Wing anti-icing system,  
   266–268, **267**
- wet sump oil/lubricating system,  
   118–121, **119, 120**
- wet-pump pneumatic systems,  
   281–283
- wheel wells, corrosion, 7
- windows (*see* transparencies)
- wobble fuel pumps, 136
- Wright 760 radial engine, **78**
- wrinkles in exterior skin, 5
- xenon flash tubes, strobe lights, 13